

Report ID: 18,561,734 Version: 1 Created: 24 Sep 2018

Make:	Chrysler Jeep	Model:	Cherokee	Body Style:	Wagon		Pass	Fail	N/A
Year:	2001	Registration:	EPS227	Reg Expiry:	02 Jan 2019	Engine	L		
WoF Expiry:	11 Sep 2019	Odometer:	182,830 Kms	Good No:	18561734	Oil level	~		
VIN:	1J4FN48S01L518984	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
	S PT P SC		S P SC SC		S SC	Performance	~		
						Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent PT SC R = rust PT SC PT = paint defect C = crack						Operation	~		
						Noise	~		
						Clutch			~
P = pin dent						CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scurs S SC S P SC S P SC S P SC S S SC						Performance	~		
Body Insr	pection Comments	Note: som	e defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
LH indicator repeater lamp not going.Taillights and number plate lamps not going.Rear wiper/washer					Tyres (lowest observed tread depth of tyres)			s)	
damaged					Left front	5 mm		mm	
Roof lining coming off.Heater controls not working properly, heater fan noisy. AC not cold.Stereo not working.Mirrors not adjusting.Headlamp switch faulty.Rear seatbelt brackets & catch rusty.						Right front	3 mm		mm
						Left rear	4 mm		mm
Conditions During Body Inspection: Dry					Right rear	5 mm		mm	
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Engine drive belt idler noisy. Surface rust on front panel brackets. Automatic transmission has oil seepage. RHR axle seal leaking. Rear dif pinion seal has seepage. Grease on edge of RF brake disc from over greasing of steering.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation		~	
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Comoto	Average					Tail lights		<	
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Deal-L	Average					Wipers (front & rear)	5		
Dashboa						Window winder FL	>		
	_					Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
Stonechips on windscreen. Battery is low. No wheel brace. Shocks have wear. Airbag lamp comes on intermittently.						Window winder RR	~		
		,				Rear view mirrors		~	
						Radio (basic test only)		<	
						CD (basic test only)		~	
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	>		
						Remote locking			~
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	ot Applicable	Kms:		Reversing camera			~
Inspected by: Roger King Date: 24 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: