

Report ID: 18,563,139 Version: 3 03 Jan 2019 Created:

Make:	Ford	Model:	Territory	Body Style:	SUV		Pass	Fail	N/A
Year:	2005	Registration:	CZE496	Reg Expiry:	02 Apr 2019	Engine	1 435	1 un	
WoF Expiry:		Odometer:	132,825 Kms	Good No:	18563139	Oil level	~		
VIN:	6FPAAAJGAT5G20217		152,625 1115	Service Histor		Smoke & fumes	~		
	011700000000000000000000000000000000000					Performance	~		
	port is not a warranty			-		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:	S	-0	ls		Р	Radiator / Hoses (visual)	~		
S = scratch	STO	A CO			X	Transmission	V		
D = dent	s sc			1n-	EID SP	Operation	~		
R = rust				10		Noise	~		
PT = paint def C = crack	ect III			+	SC	Clutch			~
P = pin dent	Htc	KI			JUII —	CV joints	~		
* = decals	s sc pp			AL-	ELIP S	Wheel bearings			
SC = stone chips						Wheel bearings			
W = significant scuffs S S W S PT									<u> </u>
		Noto: con				Performance Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								~ <b>f t</b>	
Stone chips on front windscreen						Tyres (lowest observed tread depth of tyres)			
						Left front		.0	mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Wet						Right rear	5.0		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	inage a onder bor	meemspeede	<u>Comments</u>			Suspension			<u> </u>
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			T
Interior Comments						Operation 🖌			
	Average					Electrical / Accessories			T
Seats						Head lights	~		<u> </u>
Carpets	Average					Tail lights	~		
	Average					Indicators	~		<u> </u>
Panels	/ Werage					Dashboard warning lights	~		<u> </u>
Dashboa	ard Average					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<b> </b>
General	omments					Window winder FR	~		<u> </u>
General Comments Remote control not working and button damaged						Window winder RL	~		<u> </u>
		annugeu				Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)		~	
L						Number of keys	1		
Road Con	ditions During Tes	t Drive:	Wet			Central locking	~		<b> </b>
Engine Ti	ming Mechanism:	Timing	Chain			Remote locking		~	
-	-	-		Kmc		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspecte	d by: Xinghui Lin					Date: 25 Sep 20	18		

I have read and understood this condition guide.

Name: .....

Signature: .....