

Report ID: 18,563,230 Version: 4 Created: 28 Sep 2018

Make:	Hyundai	Model:	130	Body Style:	Hatchback	וך		Pass	Fail	N/A	
Year:	2009	Registration:	HKP611	Reg Expiry:	05 Feb 2019		Engine		1		
WoF Expiry:	06 Oct 2019	Odometer:	139,360 Kms	Good No:	18563230		Oil level	~			
VIN:	KMHDB51DR9U16128	Next Service:	132,000	Service Histor	y: No		Smoke & fumes	~			
						٦ľ	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						lİ	Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System				
							Coolant condition	~			
						٦ŀ	Performance	~			
Key:	S	-0	SP S	-161-	s		Radiator / Hoses (visual)	~			
S = scratch							Transmission				
D = dent R = rust SPT SC							Operation	~			
R = rust PT = paint defect							Noise	~			
C = crack					S]	Clutch	-		~	
P = pin dent	HIG				세비		CV joints	~			
* = decals	ssc 91			- Jul	HIP	1	Wheel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs P SC W SC SC SC							Performance	~			
		Note: son	ne defects & blemishes	may not be disp	layed in the diagram		Hand Brake	~			
Body Inspection Comments							Tyres (lowest observed tread	•	of tyre	ا مر	
							Left front 6 mi				
							Right front		-	 mm	
							Left rear	0		mm	
Conditions During Body Inspections						51	Right rear			 mm	
Conditions During Body Inspection: Wet						┛╏	Right rear 3 mm Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						٦ŀ	Suspension				
							Suspension performance	~			
							Steering performance	•	~		
							Shock absorbers	~	~		
							Air Conditioning / Heater	V			
							Operation				
Interior Comments						٦.	Electrical / Accessories	V			
Seats Average							Head lights				
							Tail lights	~			
Carpets	Average						Indicators	~			
	Average										
Panels							Dashboard warning lights Wipers (front & rear)	レ レ			
Dashboa	rd Good						Window winder FL				
						┨┨	Window winder FL	v			
General Comments						וך	Window winder FR Window winder RL	v			
Steering system knocking noise							Window winder RL	レ レ			
Right electrical side mirror not working Gear knob chrome peeling shape edge need attention							Rear view mirrors	~			
Gear Knob	cmome peeling snape e	euge need attent	.001				Rear view mirrors Radio (basic test only)		~		
							CD (basic test only)	レ レ			
							Number of keys				
						╡╏	Central locking	2			
Road Conditions During Test Drive: Dry						┨┨	5				
Engine Timing Mechanism: Timing Chain						ןך	Remote locking	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:							Sat. Nav. (basic test only)			~	
							Reversing camera			~	
Inspected by: Jason Law Date: 28 Sep 2018											

I have read and understood this condition guide.

Name:

Signature: