

Report ID: 18,564,726 Version: 1 Created: 17 Sep 2018

Make:	Mazda	Model:	Demio	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2003	Registration:	DNQ926	Reg Expiry:	10 Oct 2018	Engine	1	1	L
WoF Expiry:	02 Jan 2019	Odometer:	183,934 Kms	Good No:	18564726	Oil level	~		
VIN:	7A8C12H0706215664	Next Service:	185425	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0	ls	-161-	s	Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect						Transmission			
						Operation	~		
						Noise	~		
C = crack						Clutch	•		~
P = pin dent						CV joints	~		
* = decals	SP PIC			AL.	ELARIC	Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs S W						Performance	~		
		Nataron	defects & blemishes		laved in the diagram	Hand Brake			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								ofture	
Stone chips n scratch mark front screen. Drivers door monsoon shield missing.						Tyres (lowest observed tread		-	-
						Left front		6 mm	
						Right front		5	mm
						Left rear		4	mm
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
						Suspension			
FWD.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
						Window winder FL	~		
	_]	Window winder FR	~		
General Comments						Window winder RL	~		
Right hand	park n left hand indicat	or not working.				Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		·
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
ц							1	1	
Inspected by: Eddie Marsters Date: 17 Sep 2018									
I have read and understood this condition guide. Name:									