

Report ID: 18,566,763 Version: 1 Created: 03 Oct 2018

Make:	Mazda	Model:	Mazda3	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2004	Registration: BZJ174 Reg Expiry: 09 Aug 2018			Engine	I	1	1	
WoF Expiry:	06 Sep 2019	Odometer:	177,894 Kms	Good No:	18566763	Oil level	~		
VIN:	JM0BK10F100105253	Next Service:	188000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SPSC	-0	SC SC	-161-	SC	Radiator / Hoses (visual)	v		
S = scratch						Transmission	•		<u> </u>
D = dent S = suct S SC D = S = S = S = S = S = S = S = S = S =						Operation	~		
R = rust 3.5C PT = paint defect C = crack SC						Noise	~		
						Clutch	~		
P = pin dent						CV joints	~		
* = decals SSC 919						Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs						Performance	~		
Note: come defecte & blamiches may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments								ofture	
						Tyres (lowest observed tread depth of tyres)			
						Left front		5	mm
						Right front		5	mm
						Left rear	3	-	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
onder carnage & onder bonnet inspection comments						Suspension			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation	~		
Interior Comments Average						Electrical / Accessories			
Seats	Avelage					Head lights	~		
Carpets	Average					Tail lights	~		
	A					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
Dashboa	ru –					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		•
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
							1		
Inspected by: Donovan Matara Date: 03 Oct 2018									
I have read and understood this condition guide. Name:									