

Report ID: 18,567,537 Version: 1 26 Sep 2018 Created:

Make:	Nissan	Model:	Murano	Body Style:	SUV		Pass	Fail	N/A
Year:	2006	<b>Registration:</b>	HZT761	Reg Expiry:	08 Dec 2018	Engine	1	I	1
WoF Expiry:		Odometer:	155,690 Kms	Good No:	18567537	Oil level	~		
VIN:	7AT0DH74X14005196	Next Service:	165600	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	r		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	sc sc	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	SC DI			The	BIL SC	Operation	~		
PT = paint defe				$\left[ \right] \left[ \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74114	CV joints		~	
* = decals	s sc 916			The second	ALC S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC SC SC S						Performance	~		
Podulaci		Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
								mm	
						Right front	6		mm
						Left rear		.1	mm
Conditions During Body Inspection:						Right rear	4.6 mm		
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension	103		
						Suspension performance	~		
						Steering performance	~		
Shock absorbers						~			
Air Conditioning / Heater							-		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	drivers sea	t ripped otherwi	se good			Head lights	~		
	Card					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
							· ·		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Timing Chain   Sat. Nav. (basic test only)							-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
									•
Inspected by: Ian Dunn Date: 19 Sep 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....