

Report ID: 18,567,954 Version: 1 Created: 20 Sep 2018

Make:	Holden	Model:	Barina	Body Style:	Hatchback		Pass	Fail	N/A
Year:	1994	Registration:	TL3538	Reg Expiry:	29 Jan 2019	Engine	I		
WoF Expiry:	21 Mar 2019	Odometer:	157,199 Kms	Good No:	18567954	Oil level	~		
VIN:	W0L000078S4137111	Next Service:	172,000	Service Histor	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	V		
Key:	R	-0	R SC		S SC	Radiator / Hoses (visual)	r		
S = scratch D = dent						Transmission	I		
D = dent R = rust				715	HIV SC	Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch	~		
P = pin dent	HE				74 <u>11</u> 4	CV joints	~		
* = decals	sc Ole	1		The second	ED SC	Wheel bearings		~	
SC = stone chips						Brakes			
W = significant scuffs SC S S R						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	r		
body inspection comments					Tyres (lowest observed tread depth of tyres)			es)	
					Left front		4.3 mm		
						Right front		.7	mm
						Left rear			mm
Conditions During Body Inspection: Dry						Right rear		.2	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Large engine oil leak						Suspension performance	~		
Right rear v	vheel bearing					Steering performance	V		
						Shock absorbers	r		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	V		
<u></u>	Average					Tail lights	r		
Carpets	/ Weidge					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	•					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
Inspected by: Ian Dunn Date: 20 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: