

Report ID: 18,568,013 Version: 1 11 Oct 2018 Created:

| Make: | Nissan | Model: | Maxima | Body Style: | Sedan | | Pass | Fail | N/A |
|---|--|----------------|----------------|----------------|------------------|--|--------|------|----------|
| Year: | 2009 | Registration: | KBZ723 | Reg Expiry: | 22 Oct 2018 | Engine | | | |
| WoF Expiry: | | Odometer: | 161,908 Kms | Good No: | 18568013 | Oil level | ~ | | |
| VIN: | MNTBAUJ32A0000044 | | 162000 | Service Histor | | Smoke & fumes | ~ | | |
| | MITTE/(0552/(000001- | | 102000 | | 103 | Performance | ~ | | |
| | port is not a warranty | | с I II | D | | Noise | ~ | | |
| | a guide only. Conside sting undertaken. The | | | | | Cooling System | • | | |
| | ical inspection prior to | | | | | Coolant condition | ~ | | |
| | | _ | | | | Performance | ~ | | |
| Key: | s w | -0 | SP S | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | s sc w | | | 1n- | EID S | Operation | ~ | | |
| R = rust | | | | 10 | THIA | Noise | ~ | | |
| PT = paint def C = crack | ect M | | | | S W | Clutch | | | ~ |
| P = pin dent | Ho | | | | | CV joints | ~ | | |
| * = decals | - MIK | | | AL- | ELIP S | Wheel bearings | | | |
| SC = stone chips | | | | | | Brakes | ~ | | |
| W = significant scuffs S W S S S W S | | | | | | | | | |
| | | | | | | | ~ | | |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | Hand Brake | | | |
| Stone chips front screen. | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | 3. | | mm |
| | | | | | | Right front | | 3 | mm |
| | | | | | | Left rear | 3. | - | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 4.5 mm | | |
| Under Carriage & Under Report Inspection Comments | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| FWD. Engi | ne n trans fluid leak. | | | | | Suspension performance | ~ | | <u> </u> |
| | | | | | | Steering performance | ~ | | <u> </u> |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| Interior Comments | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| Carpets | Good | | | | | Tail lights | ~ | | |
| | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| Dashboa | Good | | | | | Wipers (front & rear) | ~ | | |
| Dashbud | | | | | | Window winder FL | ~ | | |
| <u> </u> | | | | | | Window winder FR | ~ | | |
| <u>General Comments</u> | | | | | Window winder RL | ~ | | | |
| Brake noise | in reverse light pedal. | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | - |
| Road Con | ditions During Test | : Drive: | Dry | | | Central locking | ~ | | |
| | - | | - | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| | | | | | | | | | |
| Inspected by: Eddie Marsters | | | | | | Date: 11 Oct 20 | 18 | | |
| I have read | and understood th | is condition o | juide. Name: . | | | Signature: | | | |