

Report ID: 18,568,032 Version: 1 20 Sep 2018 Created:

Make:	Nissan	Model:	Wingroad	Body Style:	Wagon		Pass	Fail	N/A
Year:	2010	Registration:	LMB80	Reg Expiry:	01 Jan 2019	Engine	1		<u> </u>
	02 Oct 2019	Odometer:	80,316 Kms	Good No:	18568032	Oil level	~		
VIN:	7AT0DH5GX18029378	Next Service:	82,715kms	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		6	Dauta have used	harry alternatively at an	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- HE			The	SDW	Operation	~		
R = rust PT = paint def				$\prod$	JUIL	Noise	~		
C = crack				$+ \mathbf{\nabla}$	w	Clutch			~
P = pin dent					세비	CV joints	~		
* = decals	sc 916			The		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	•	of tyre	es)
Small dent in bottom of left rear bumper. Scratches on right side & left side sills.					Left front 4.6 mm				
						Right front		.0	mm
						Left rear		.0	mm
Condition	as During Body Inst	oction:	Deri			Right rear			mm
Conditions During Body Inspection: Dry						Right rear 5.8 mm   Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Front brake	pads wearing low.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		<u> </u>
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		+
	1				I	Window winder FR	~		<u> </u>
General Comments						Window winder RL	~		+
Drivers seat has movement in seat rails.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		1
Road Conditions During Test Drive: Dry						Central locking	~		
			Jy			Remote locking	~		
Engine Ti	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
							1		
Inspecte	d by: Jason Young					Date: 19 Sep 20	18		

I have read and understood this condition guide.

Name: .....

Signature: .....