

Basic Vehicle Condition Guide

Report ID: 51,711


Version: 3

Created: 20 Dec 2018

Make: Model: Holden Commodore **Body Style:** Wagon Year: 2014 Registration: HPZ280 Reg Expiry: 17 Feb 2019 WoF Expiry: **Odometer: Good No:** 17 Oct 2019 158,671 Kms 18569347 VIN: 6G1FB8E39EL994610 **Next Service: Just Serviced Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | |
|-------------------|------|--|
| Seats | Good | |
| Carpets | Good | |
| Panels | Good | |
| Dashboard | Good | |

General Comments

Inspected by:

2 x Keys but one remote has key blade separate Split in D/Seat back bolster

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

| | Pass | Fail | N/A | |
|---------------------------------------|--|---------|----------|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | ~ | | | |
| Performance | V | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ' | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | l depth | of tyre | L es) | |
| Left front | | .0 | mm | |
| Right front | | .0 | mm | |
| Left rear | | .0 | mm | |
| Right rear | | | mm | |
| Spare | 7.0 mm Yes | | | |
| Suspension | | 103 | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | <i>y</i> | | | |
| Indicators | <i>y</i> | | | |
| Dashboard warning lights | · · | | | |
| Wipers (front & rear) | \(\times \) \(\t | | | |
| Window winder FL | · · | | | |
| Window winder FR | | | | |
| Window winder RL | VVV | | | |
| Window winder RR | ·/ | | - | |
| Rear view mirrors | <i>y</i> | | | |
| Radio (basic test only) | <i>'</i> | | | |
| CD (basic test only) | <i>v</i> | | | |
| Number of keys | | | | |
| . DANINGE OF ACAS | 7 | | | |
| · · · · · · · · · · · · · · · · · · · | 2 | | 1 | |
| Central locking | 2 V | | | |
| Central locking Remote locking | | | | |
| Central locking | | | <i>V</i> | |

I have read and understood this condition guide.

| Name [.] | |
|-------------------|--|
| | |

Signature:

Date: 27 Sep 2018