

Report ID: 18,570,028 Version: 1 20 Sep 2018 Created:

| Make:  | Daihatsu           | Model:        | Charade     | Body Style:     | Hatchback   |  | Pass | Fail | N/A |  |
|--|--------------------|---------------|-------------|-----------------|-------------|--|------|------|-----|--|
| Year:  | 2005               | Registration: | DAB413      | Reg Expiry:     | 24 Jan 2019 | Engine                                       |      |      |     |  |
| l  | 15 Feb 2019        | Odometer:     | 159,900 Kms | Good No:        | 18570028    | Oil level                                    | ~    |      |     |  |
| VIN:   | JDAL251S001044722  |               | 151000      | Service History |             | Smoke & fumes                                | ~    |      |     |  |
|  | JDAL2313001044722  |               | 151000      |                 | · 110       | Performance                                  | ~    |      |     |  |
| Note: This report is not a warranty  |                    |               |             |                 |             | Noise  | ~    |      |     |  |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. |                    |               |             |                 |             | Cooling System                               |      |      |     |  |
|  |                    |               |             |                 |             | Coolant condition                            | ~    |      |     |  |
|  |                    |               |             |                 |             | Performance                                  | ~    |      |     |  |
| Key:   |                    | -0            | S D SC SC   |                 |             | Radiator / Hoses (visual)                    | -    |      |     |  |
| S = scratch  |                    |               |             |                 |             | Transmission                                 | ~    |      |     |  |
| D = dent   |                    |               |             |                 |             |  |      |      |     |  |
| R = rust   |                    |               |             | 10              |             | Operation                                    | ~    |      |     |  |
| PT = paint defect  |                    |               |             |                 |             | Noise  | ~    |      |     |  |
| C = crack P = pin dent   |                    |               |             |                 |             | Clutch                                       | ~    |      |     |  |
| * = decals SC P/P  |                    |               |             |                 |             | CV joints                                    | ~    |      |     |  |
| SC = stone chips   |                    |               |             |                 |             | Wheel bearings                               | ~    |      |     |  |
| W = significant scuffs   |                    |               |             |                 |             | Brakes                                       |      |      |     |  |
|  |                    |               |             |                 |             | Performance                                  | ~    |      |     |  |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram  |                    |               |             |                 |             | Hand Brake                                   | ~    |      |     |  |
| Stone chips front screen. Trim missing off drivers seat adjuster   |                    |               |             |                 |             | Tyres (lowest observed tread depth of tyres) |      |      |     |  |
|  |                    |               |             |                 | Left front  | 4  | 4 mm |      |     |  |
|  |                    |               |             |                 |             | Right front                                  |      | 5    | mm  |  |
|  |                    |               |             |                 |             | Left rear                                    |      | 5    | mm  |  |
| Conditions During Body Inspection: Dry   |                    |               |             |                 |             | Right rear                                   |      | 5    | mm  |  |
|  |                    |               |             |                 |             | Spare Yes                                    |      |      |     |  |
| Under Carriage & Under Bonnet Inspection Comments  |                    |               |             |                 |             | Suspension                                   | 1    |      | -   |  |
|  |                    |               |             |                 |             | Suspension performance                       | ~    |      |     |  |
|  |                    |               |             |                 |             | Steering performance                         | ~    |      |     |  |
|  |                    |               |             |                 |             | Shock absorbers                              | ~    |      |     |  |
|  |                    |               |             |                 |             | Air Conditioning / Heater                    | -    |      |     |  |
|  |                    |               |             |                 |             | Operation                                    | ~    |      |     |  |
| Interior Comments  |                    |               |             |                 |             | Electrical / Accessories                     |      |      |     |  |
| Seats  | Good               |               |             |                 |             | Head lights                                  | ~    |      |     |  |
| Correcto   | Average            |               |             |                 |             | Tail lights                                  | ~    |      |     |  |
| Carpets  |                    |               |             |                 |             | Indicators                                   | ~    |      |     |  |
| Panels   | Good               |               |             |                 |             | Dashboard warning lights                     | ~    |      |     |  |
|  | , Good             |               |             |                 |             | Wipers (front & rear)                        | ~    |      |     |  |
| Dashboa  | rd                 |               |             |                 |             | Window winder FL                             | ~    |      |     |  |
|  |                    |               |             |                 |             | Window winder FR                             | ~    |      |     |  |
| General C  | <u>Comments</u>    |               |             |                 |             | Window winder RL                             | ~    |      |     |  |
|  |                    |               |             |                 |             | Window winder RR                             | ~    |      |     |  |
|  |                    |               |             |                 |             | Rear view mirrors                            | ~    |      |     |  |
|  |                    |               |             |                 |             | Radio (basic test only)                      | ~    |      |     |  |
|  |                    |               |             |                 |             | CD (basic test only)                         | ~    |      |     |  |
|  |                    |               |             |                 |             | Number of keys                               | 2    |      | L   |  |
| Road Conditions During Test Drive: Dry   |                    |               |             |                 |             | Central locking                              | ~    |      |     |  |
|  |                    |               |             |                 |             | Remote locking                               |      |      | ~   |  |
| Engine Timing Mechanism: Cambelt   |                    |               |             |                 |             | Sat. Nav. (basic test only)                  |      |      | ~   |  |
| Evidence   | of Cam Belt Replac | ement: N      | lo          | Kms:            |             | Reversing camera                             |      |      | ~   |  |
|  |                    |               |             |                 |             |  | 1    |      |     |  |
| Inspected by: Brian Hill Date: 20 Sep 2018   |                    |               |             |                 |             |  |      |      |     |  |
| I have read and understood this condition guide. Name:   |                    |               |             |                 |             |  |      |      |     |  |