

I have read and understood this condition guide.

Report ID: 18,571,072 Version: 1 Created: 23 Oct 2018

Signature: .....

Make:	Suzuki	Model:	SX4	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2009	<b>Registration:</b>	EZL929	Reg Expiry:	19 Jul 2019	Engine	1	<u> </u>	L
WoF Expiry:	28 Sep 2019	Odometer:	157,613 Kms	Good No:	18571072	Oil level	V		
VIN:	JSAGYA41S00111444	Next Service:	167600	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	V		
	port is not a warranty	avation is made	for one and miles as	Dauta hava nat	heen dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	S SC SC		S D SC	Radiator / Hoses (visual)	~		
S = scratch	STE	A CO			X	Transmission	•		
D = dent	s sc			the	EL SC	Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack				+		Clutch	~		
P = pin dent						CV joints	~		
* = decals	sc pip			AL-	ENR	Wheel bearings			
SC = stone chips						Brakes	~		
W = significant scuffs SC S SC S SC S SC S									
		Net				Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake			
						Tyres (lowest observed tread depth of tyres)			
						Left front	6	5	mm
						Right front	e	5	mm
						Left rear	e	5	mm
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
						Spare Yes			
Under Ca	rriage & Under Bor	net Inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	V		
Panels	Good					Dashboard warning lights	V		
<u> </u>	. Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	-				J	Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	V		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
Road Conditions During Test Drive: Drv						Central locking	2 V		
	uning resi		Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)			~
-	of Cam Belt Replac		lot Applicable	Kms:		Reversing camera			~
		P							~
Inspected by: Donovan Matara Date: 23 Oct 2018									

Name: .....