

Report ID: 18,572,894 Version: 2 Created: 09 Oct 2018

| Make:  | Nissan                   | Model:               | Urvan                  | Body Style:       | Van                  |  | Pass | Fail | N/A |
|--|--------------------------|----------------------|------------------------|-------------------|----------------------|--|------|------|-----|
| Year:  | 2011                     | <b>Registration:</b> | GAN544                 | Reg Expiry:       | 25 Sep 2018          | Engine                                       |      |      | L   |
| WoF Expiry:  | 04 Oct 2019              | Odometer:            | 148,487 Kms            | Good No:          | 18572894             | Oil level                                    | ~    |      |     |
| VIN:   | JN1MG2E25Z0760455        | Next Service:        | 158000                 | Service Histor    | <b>y:</b> No         | Smoke & fumes                                | ~    |      |     |
|  |                          |                      |                        |                   |                      | Performance                                  | ~    |      |     |
|  | port is not a warranty   | pration is made      | for age and mileage    | Parts have not    | been dismantled or   | Noise  | ~    |      |     |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. |                          |                      |                        |                   |                      | Cooling System                               |      |      |     |
| a full mechan  | ical inspection prior to | purchase and th      | his can be arranged fo | r an additional o | charge.              | Coolant condition                            | ~    |      |     |
|  | SC                       |                      | S D D                  |                   | S D                  | Performance                                  | ~    |      |     |
| Key:   | ISC IC                   | -0                   |                        | 500-              | 30                   | Radiator / Hoses (visual)                    | ~    |      |     |
| S = scratch<br>D = dent  |                          |                      |                        |                   |                      | Transmission                                 |      |      |     |
| B = rust   |                          |                      |                        |                   |                      | Operation                                    | ~    |      |     |
| PT = paint defect  |                          |                      |                        |                   |                      | Noise  | ~    |      |     |
| C = crack  |                          |                      |                        |                   |                      | Clutch                                       |      |      | ~   |
| P = pin dent   |                          |                      |                        |                   |                      | CV joints                                    | ~    |      |     |
| *= decals  |                          |                      |                        |                   |                      | Wheel bearings                               | ~    |      |     |
| SC = stone chips<br>W = significant scuffs   |                          |                      |                        |                   |                      | Brakes                                       |      |      |     |
| w = significant scuris   |                          |                      |                        |                   |                      | Performance                                  | ~    |      |     |
| Body Insr  | pection Comments         | Note: som            | ne defects & blemishes | may not be disp   | layed in the diagram | Hand Brake                                   | ~    |      |     |
| Rear bumper not fitted correctly   |                          |                      |                        |                   |                      | Tyres (lowest observed tread depth of tyres) |      |      |     |
|  |                          |                      |                        |                   |                      | Left front                                   | 8    |      | mm  |
|  |                          |                      |                        |                   |                      | Right front                                  | 8    | 3    | mm  |
|  |                          |                      |                        |                   |                      | Left rear                                    | 8    | 3    | mm  |
| Conditions During Body Inspection: Dry   |                          |                      |                        |                   |                      | Right rear                                   | 8 mi |      | mm  |
|  |                          |                      |                        |                   |                      | Spare  | Yes  |      |     |
| Under Carriage & Under Bonnet Inspection Comments  |                          |                      |                        |                   |                      | Suspension                                   |      |      |     |
| Rear wiper not working   |                          |                      |                        |                   |                      | Suspension performance                       | ~    |      |     |
| Oil leak<br>Underbody oxidisation  |                          |                      |                        |                   |                      | Steering performance                         | ~    |      |     |
|  |                          |                      |                        |                   |                      | Shock absorbers                              | ~    |      |     |
|  |                          |                      |                        |                   |                      | Air Conditioning / Heater                    |      |      |     |
|  |                          |                      |                        |                   |                      | Operation 🖌                                  |      |      |     |
| Interior Comments  |                          |                      |                        |                   |                      | Electrical / Accessories                     |      |      |     |
| Seats  | Stains on s              | eats,hole in drive   | ers seat               |                   |                      | Head lights                                  | ~    |      |     |
|  | Holes and                | stains on carpets    | 5                      |                   |                      | Tail lights                                  | ~    |      |     |
| Carpets  |                          |                      |                        |                   |                      | Indicators                                   | ~    |      |     |
| Panels   | Average                  |                      |                        |                   |                      | Dashboard warning lights                     | ~    |      |     |
| Deathle  | Average                  |                      |                        |                   |                      | Wipers (front & rear)                        |      | ~    |     |
| Dashboa  | ru y                     |                      |                        |                   |                      | Window winder FL                             | ~    |      |     |
|  | -                        |                      |                        |                   |                      | Window winder FR                             | ~    |      |     |
| General Comments   |                          |                      |                        |                   |                      | Window winder RL                             |      |      | ~   |
|  |                          |                      |                        |                   |                      | Window winder RR                             |      |      | ~   |
|  |                          |                      |                        |                   |                      | Rear view mirrors                            | ~    |      |     |
|  |                          |                      |                        |                   |                      | Radio (basic test only)                      | ~    |      |     |
|  |                          |                      |                        |                   |                      | CD (basic test only)                         | ~    |      |     |
|  |                          |                      |                        |                   |                      | Number of keys                               | 1    |      |     |
| Road Conditions During Test Drive: Wet   |                          |                      |                        |                   |                      | Central locking                              | ~    |      |     |
|  |                          |                      |                        |                   |                      | Remote locking                               | ~    |      |     |
| Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test or   |                          |                      |                        |                   |                      |  |      |      | ~   |
| Evidence of Cam Belt Replacement: Not Applicable Kms:  |                          |                      |                        |                   |                      | Reversing camera                             |      |      | ~   |
| Inspected by: John Lindsay Date: 09 Oct 2018   |                          |                      |                        |                   |                      |  |      |      |     |

I have read and understood this condition guide.

Name: .....

Signature: .....