

Report ID: 18,573,641 Version: 1 Created: 03 Oct 2018

Make:	Mitsubishi	Model:	L300	Body Style:	Van		Pass	Fail	N/A
Year:	2012	Registration:	GNF283	Reg Expiry:	25 Sep 2018	Engine	1		1
WoF Expiry:	29 Sep 2019	Odometer:	79,815 Kms	Good No:	18573641	Oil level	~		
VIN:	JMAHNP14VDA80024	Next Service:	78,000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage.	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and tr	his can be arranged to	r an additional c	inarge.	Coolant condition	~		
	SC		S			Performance	~		
Key:		=		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission	1		1
R = rust	s AR			210		Operation	~		
PT = paint def	ect NP				11111	Noise	~		
C = crack					R SC W	Clutch	~		
P = pin dent	sc dle				2416	CV joints			~
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
significant scurs s						Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front 3			mm
						Right front	4	ļ	mm
						Left rear		3	mm
Conditions During Body Inspection: Dry						Right rear	ght rear 4		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
						Window winder FL	~		
Canada						Window winder FR	~		<u> </u>
General Comments Rattling from exhaust muffler/ pipe						Window winder RL			~
Minor engine vibration in idle						Window winder RR			~
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking			~
Engine Timing Mechanism: Cambelt						Remote locking			~
						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
Inspected by: Mathew Varghese Date: 03 Oct 2018									

I have read and understood this condition guide.

Name:

Signature: