

Report ID: 18,573,809


Version:

Created: 24 Sep 2018

Make:	Toyota	Model:	Hiace	Body Style:	Van
Year:	2014	Registration:		Reg Expiry:	
WoF Expiry:	18 Sep 2019	Odometer:	126,399 Kms	Good No:	18573809
VIN:	7AT0H60FX18143281	Next Service:	136396	Service History	y: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Commen	<u>ts</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** No

Fail N/A Pass Engine Oil level Smoke & fumes ~ Performance Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation 1 Noise 1 Clutch ~ CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front mm Left rear 3 mm Right rear mm 4 Spare Yes Suspension Suspension performance Steering performance V Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories Head lights** Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR 1 Window winder RL Window winder RR ~ Rear view mirrors 1 Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera ~

I have read and understood this condition guide.

John Lindsay

Name:

Kms:

Signature:

24 Sep 2018

Date: