

Report ID: 51,715 Version: 1 Created: 08 Oct 2018

Make:	Mazda	Model:	Mazda3	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2011	Registration:	FUP609	Reg Expiry:	03 Apr 2019	Engine			
WoF Expiry:	09 Oct 2019	Odometer:	162,375 Kms	Good No:	18575448	Oil level	~		
VIN:	JM0BL10F100210169	Next Service:	Just Serviced	Service Histor	y: Yes	Smoke & fumes	~		
Note: This report is not a warranty						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic te	sting undertaken. The lical inspection prior to	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System			
			ins can be analiged to		indige.	Coolant condition	~		
Kow	SC	5		\sim		Performance	~		
Key: S = scratch		$\overline{(0)}$		5(O)7		Radiator / Hoses (visual)	~		
						Transmission	Transmission		
R = rust	sc 96				HIV	Operation	~		
PT = paint def	ect N					Noise	~		
C = crack						Clutch			~
P = pin dent * = decals	sc dk			SI_	出版	CV joints	~		
SC = stone chi		10		70		Wheel bearings	~		
W = significant scuffs						Brakes			
						Performance	~		<u> </u>
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	4	.0	mm
						Right front	4	.0	mm
						Left rear	4	.0	mm
Conditions During Body Inspection: Dry						Right rear	4	4.0 m	
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes .		
	inage & onder boi	metinspectic	<u>In comments</u>			Suspension			1
						Suspension performance			
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		T
Interior Comments						Operation 🖌			
	Good	Electrical / Accessories							
Seats						Head lights	·		+
Carpets	Good					Tail lights Indicators	v		+
	Good								+
Panels						Dashboard warning light			+
Dashboa	rd Good					Wipers (front & rear) Window winder FL	v		+
						Window winder FL	V		+
General Comments						Window winder FR Window winder RL	~ ~		+
						Window winder RL Window winder RR	~ ~		+
						Rear view mirrors	~ ~		+
						Radio (basic test only)	~ ~		+
						CD (basic test only)	~ ~		+
						Number of keys	2		<u> </u>
Road Conditions During Test Drive: Drv						Central locking	2 V		1
Road Conditions During Test Drive: Dry						Remote locking	~		+
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
	-	-							
Inspected by: SCOTT Date: 27 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: