

Report ID: 5,567 Version: 2 Created: 02 Oct 2018

Make:	Skoda	Model:	Octavia	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2013	Registration:	GUE570	Reg Expiry:	23 Jul 2019	Engine				
WoF Expiry:	09 Oct 2019	Odometer:	18,094 Kms	Good No:	18575513	Oil level	~			
VIN:	TMBCJ61Z9D2064428	Next Service:	DUE	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and t	his can be arranged to	or an additional o	narge.	Coolant condition	~			
	SC		SC SC			Performance	~			
Key:	ISC IC	-0	sc sc			Radiator / Hoses (visual)	~		<u> </u>	
S = scratch D = dent						Transmission				
D = dent R = rust	sc			710	HIV	Operation	~			
PT = paint defe		r I		$\left(\left \left(\right) \right\rangle \right)$		Noise	~			
C = crack						Clutch			~	
P = pin dent	HID				74116	CV joints	~			
* = decals	sc 916					Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs SC SC SC SC						Performance	~			
Body Incr	Pection Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		1	
Body Inspection Comments SERVICE DUE						Tyres (lowest observed tread depth of tyres)				
									mm	
						Right front	6		mm	
						Left rear	6		mm	
Conditio	ns During Body Ins	oection [.]	Dry			Right rear	6		mm	
	Spare Yes									
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~		1	
						Shock absorbers	~			
						Air Conditioning / Heater	1		1	
L						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
	Good					Tail lights	~			
Carpets						Indicators	~		1	
Panels	Good					Dashboard warning lights	~		1	
	, Good					Wipers (front & rear)	~		1	
Dashboa	rd					Window winder FL	~		1	
	•					Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~		1	
						Window winder RR	~		1	
						Rear view mirrors	~		1	
						Radio (basic test only)	~		1	
						CD (basic test only)	~	C	1	
						Number of keys	2		1	
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected by: SCOTT Date: 27 Sep 2018										

I have read and understood this condition guide.

Name:

Signature: