

Report ID: 18,575,584 Version: 2 Created: 26 Sep 2018

Make:	Hyundai	Model:	Accent	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2015	Registration:	JHU967	Reg Expiry:	07 Dec 2018	Engine			
WoF Expiry:	08 Sep 2019	Odometer:	30,428 Kms	Good No:	18575584	Oil level	~		
VIN:	KMHCT51DMFU23456	Next Service:	45000	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		<b>C</b> 1 1	<b>D</b> ( )		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
		_				Performance	~		
Key:		-0	LP		S	Radiator / Hoses (visual)	~		
S = scratch	STE	A CO			XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	Transmission	•		
D = dent	s dit			The	EID S	Operation	~		
R = rust PT = paint def				$\int$	JHIH	Noise	~		
C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		•
* = decals	sc 916			AL.	EITR	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W P S						Performance			
		Noto: com	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments	10000.3011	le delects & blemisnes	indy not be disp	ayed in the diagram			ofturo	) )
					Tyres (lowest observed tread depth of tyres)   Left front $\Delta$ mm				
						Right front		1	mm
						Left rear		1	mm
								2	mm
Conditions During Body Inspection: Dry						Right rear			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage a onder bor	<u>incernspectie</u>	connents			Suspension			
						Suspension performance Steering performance	~		
							~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation			
Good						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General	omments					Window winder FR	~		
General Comments Only one remote working					Window winder RL	~			
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry							~		
Engine Ti	ming Mechanism	T:	Chain			Remote locking	~		
Engine Timing Mechanism:   Timing Chain     Evidence of Cam Belt Replacement:   Not Applicable   Kms:     Beversing camera									~
Evidence	ог сапт вен керіас	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: John Lindsay Date: 26 Sep 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....