

Report ID: 18,576,099 Version: 1 26 Sep 2018 Created:

Make:	Mazda	Model:	Verisa	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2004	Registration:	HZF498	Reg Expiry:	08 Mar 2019	Engine			·
WoF Expiry:	02 Mar 2019	Odometer:	67,580 Kms	Good No:	18576099	Oil level	~		
VIN:	7AT0C103X15108856	Next Service:	75000	Service History	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	w dla			The		Operation	~		
PT = paint defe				$\left[\right] \left[\right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74 <u>11</u>	CV joints	~		-
* = decals	- 91E			The	ALL S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs S W		\square			Performance	~		
		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
	pection Comments			, ,	, ,	Tyres (lowest observed tread	-	of tvre	s)
Stone chips front screen.									mm
						Right front	5		mm
						Left rear	6		mm
Condition	as During Pody Inc	naction	D			Right rear	6		 mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension Yes			
	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		L
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
50005						Tail lights	~		
Carpets	Good					Indicators	~		
Banolo	Good					Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Navigation system is jap import						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
Road Conditions During Test Drive: Drv						Central locking	2 V		
Road Con	unions During Test	L Drive:	Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)	-		~
-	of Cam Belt Replac		lot Applicable	Kms:		Reversing camera			~
									•
Inspecte	d by: Brian Hill					Date: 26 Sep 20	18		

I have read and understood this condition guide.

Name:

Signature: