

Report ID: 18,578,677 Version: 2 20 Feb 2019 Created:

Make:	Hyundai	Model:	Getz	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2008	Registration:	ESN219	Reg Expiry:	23 Jan 2019	Engine	1	1	1
WoF Expiry:	25 Jan 2020	Odometer:	105,287 Kms	Good No:	18578677	Oil level	~		
VIN:	KMHBT51DR9U85807	Next Service:	114000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	r		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	V		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	s w	-0	S S	-161-		Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect C = crack						Transmission			
						Operation	~		
						Noise	~		
						Clutch			~
P = pin dent						CV joints	~		-
* = decals S D R SC P P S PT						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S R S W S							erformance 🖌		
Note: come defects % blamiches may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	ofture	
						Tyres (lowest observed tread depth of tyres)			
							3.0		mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Wet						Right rear	3.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
under windscreen (firewall) cowl rusty						Suspension			
under wind	screen (firewall) cowi ru	isty				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Interior Comments Average						Electrical / Accessories	1		
Seats	Avelage					Head lights	~		
Carpets	Average					Tail lights	~		
	A					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
Dashboa	iru					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
One remote control not working Drive belt noisy						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
·									
Inspected by: Xinghui Lin Date: 01 Oct 2018									
I have read and understood this condition guide. Name:									