

Basic Vehicle Condition Guide

Report ID: 18,578,988


Version: 2

Created: 20 Jun 2019

Make: Model: Hyundai Getz **Body Style:** Hatchback Year: 2007 Registration: EGC349 Reg Expiry: 04 Sep 2019 **Odometer:** WoF Expiry: 28 Nov 2018 105,141 Kms **Good No:** 18578988 VIN: KMHBT51DR8U76161 Next Service: 112000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Front bumper misaligned

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Wing mirror not working

Inspected by:

Check engine light on battery very flat

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Bobby Zhong

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance		~		
Noise	~			
Cooling System				
Coolant condition	V			
Performance	~			
Radiator / Hoses (visual)	V			
Transmission				
Operation	V			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	<i>y</i>			
Brakes				
Performance	~			
Hand Brake	<i>y</i>			
Tyres (lowest observed tread depth of tyres)				
Left front 5 mm				
Right front			mm	
Left rear	5		mm	
Right rear			mm	
Spare	5 mm Yes			
Suspension Yes				
Suspension performance	V			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	V			
Tail lights	~			
Indicators	~			
Dashboard warning lights		~		
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	~			
Window winder RL	\(\times \)			
Window winder RR	~			
Rear view mirrors				
Radio (basic test only)	V			
CD (basic test only)	~			
Number of keys	2		<u> </u>	
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera			~	
Date: 20 Jun 2019				

I have read and understood this condition guide.

Name:

Signature: