

Basic Vehicle Condition Guide

Report ID: 18,579,559

Version: 1

Engine

Oil level

Created: 04 Oct 2018

Pass


Fail

N/A

Make: Model: Suzuki APV **Body Style:** Van Year: 2007 Registration: EEQ756 Reg Expiry: 29 May 2019 WoF Expiry: **Odometer: Good No:** 15 Aug 2019 18579559 56,493 Kms VIN: MHYGDN71V0010617 **Next Service: Service History:** 60,000kms

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Small hole in plastic trim on right rear guard, by right rear tail light. Small dent in left side sill.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Average			
Carpets	Average			
Panels	Good			
Dashboard	Average			

General Comments

Inspected by:

Large hole in carpet in drivers side of cab. Drivers seat cover is starting to crack.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Jason Young

Evidence of Cam Belt Replacement: No Kms:

Date: 04 Oct 201

Smoke & fumes	~					
Performance	~					
Noise	~					
Cooling System						
Coolant condition	~					
Performance	~					
Radiator / Hoses (visual)	~					
Transmission						
Operation	~					
Noise	<i>V</i>					
Clutch	~					
CV joints			~			
Wheel bearings	~					
Brakes						
Performance	~					
Hand Brake	~					
Tyres (lowest observed tread	d depth	of tyre	es)			
Left front	8	.1	mm			
Right front	8	.4	mm			
Left rear	6	.8	mm			
Right rear	4.0		mm			
Spare	Yes					
Suspension	•					
Suspension performance	~					
Steering performance	<i>V</i>					
Shock absorbers	~					
Air Conditioning / Heater						
Operation	~					
Electrical / Accessories			•			
Head lights	~					
Tail lights	~					
Indicators	~					
Dashboard warning lights	~					
Wipers (front & rear)	\(\triangle \)					
Window winder FL	~					
Window winder FR	~					
Window winder RL			~			
Window winder RR			~			
Rear view mirrors	~					
Radio (basic test only)	~					
CD (basic test only)	~					
Number of keys	2					
Central locking	~					
Remote locking			~			
Sat. Nav. (basic test only)			~			
Reversing camera			~			
Date: 04 Oct 2019						
Date: 04 Oct 2018						

I have read and understood this condition guide.

Name:		