

Report ID: 18,579,674

Version:

Engine Oil level Smoke & fumes

Noise

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL

Window winder RR

Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Operation

**Head lights** Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 02 Oct 2018

Fail

N/A

~

mm

mm

mm

 $\mathsf{mm}$ 

3

3

V

/

1

V

1

2

Yes

Pass

~

/

1


1

Tyres (lowest observed tread depth of tyres)

Make:	Hyundai	Model:	Getz	Body Style:	Hatchback
Year:	2007	Registration:	EDK497	Reg Expiry:	24 Dec 2018
WoF Expiry:	10 Aug 2019	Odometer:	101,186 Kms	Good No:	18579674
VIN:	KMHBT51DR8U73028	Next Service:	112,917	Service History: Yes	

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Scratch on front windscreen

Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Brake fluid reservoir cap missing

Interior Comments					
Seats	Average				
Carpets	Average				
Panels	Average				
Dashboard	Good				

## **General Comments**

Drive belt noisy

Inspected by:

Road Conditions During Test Drive: Wet

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** No

Mathew Varghese

I have read and understood this condition guide.

	Remote locking	V					
	Sat. Nav. (basic test only)		~				
Kms:	Reversing camera		~				
Date: 02 Oct 2018   Name: Signature:							