

Basic Vehicle Condition Guide

Report ID: 18,581,934


Version: 1

Created: 01 Oct 2018

Make: Model: Nissan Caravan **Body Style:** Van Year: 2007 Registration: Reg Expiry: **WoF Expiry: Odometer: Good No:** 178,751 Kms 10 Aug 2019 18581934 VIN: 7AT0DH06X18000328 **Next Service: Service History:** Unknown

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Dry

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Hole in drivers footwell		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Murray Craig Date: 01 Oct 2018

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System		•	
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	_		<u> </u>
Tyres (lowest observed tread	d depth	of tyre	⊥ es)
Left front	T		mm
Right front	6		mm
Left rear	6		mm
Right rear		<u> </u>	mm
Spare	Yes		
Suspension		103	
Suspension performance	~		
Steering performance	~		1
Shock absorbers	<i>'</i>		+
Air Conditioning / Heater			1
Operation			Т
Electrical / Accessories			
Head lights			Т
Tail lights	V		
Indicators	1		
	V		
Dashboard warning lights	<i>'</i>		
Wipers (front & rear)	~		
Window winder FL	<i>'</i>		
Window winder FR	~		<u> </u>
Window winder RL			~
Window winder RR			~
Rear view mirrors	-		
Radio (basic test only)	'		
CD (basic test only)			'
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			1

I have read and understood this condition guide.

Name:

Signature: