

Report ID: 18,582,362 Version: 1 Created: 03 Oct 2018

Make:	Mazda	Model:	Capella	Body Style:	Sedan		Pass	Fail	N/A
Year:	1998	Registration:	EAH452	Reg Expiry:	14 Mar 2019	Engine	I	1	1
WoF Expiry:		Odometer:	238,580 Kms	Good No:	18582362	Oil level		~	
VIN:	7A8C10R0707106018	Next Service:	- ,	Service Histor	<b>y:</b> No	Smoke & fumes	~	-	
						Performance	~		
	port is not a warranty	avation is maada	for one and miles as	Danta hava nat	hoon dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition		~	1
						Performance	~	•	
Key:	S D SC S	-0	S P SC S D SC		S D SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission	•		
D = dent	s sc			The	BID SDC	Operation	~		1
R = rust				10	THIA	Noise	~		
PT = paint def C = crack				+		Clutch	-		~
P = pin dent	Ho	KI				CV joints	~		
* = decals	SPSC DE			AL-	ELIP S	Wheel bearings			
SC = stone chips						Brakes	~		
W = significant scuffs S SC S S S S S S S S S S S S S S S S S									1
		Noto: con					~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake			
LR tail light cracked ,						Tyres (lowest observed tread depth of tyres)			
						Left front		1	mm
						Right front		5	mm
						Left rear		1	mm
Conditions During Body Inspection: Dry						Right rear	4	1	mm
Under Carriage & Under Report Inspection Comments							Spare Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor oil le	ак,					Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater	1		
Interior Comments						Operation		~	
Interior Comments Average						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	middle co	nsole lid broken	,			Dashboard warning lights	~		
Deal-	Average					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
Has 2 keys l	out only 1 opens the do	or ,				Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)		~	
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
,						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
								í	
Inspected by: Donovan Matara Date: 03 Oct 2018									
I have read	and understood th	is condition c	juide. Name: .			Signature:			