


Report ID: 18,582,481

Version: 5

05 Feb 2019 Created:

Not



<u>B</u>

Interior Comments					
Seats	Good				
Carpets	Good				
Panels	Good				
Dashboard	Good				

Inspected by:

Ro

En

Jason Young

I have read and understood this condition guide.

	CD (basic test only)		~	
	Number of keys	1		
	Central locking	~		
	Remote locking	~		
	Sat. Nav. (basic test only)			~
Kms:	Reversing camera			~
	Date: 02 Oct 20	18		
Name:	Signature:			

e:	Ford	Model:	Focus	Body Style:	Wagon		Pass	Fail	N/A
:	2013	Registration: GST502 Reg Expiry: 26 Feb 2019			Engine	.1			
Expiry:	11 May 2019	Odometer:	69,936 Kms	Good No:	18582481	Oil level	~		
	WF0LXXGCBLCL41008	Next Service:	82,000kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~		
nostic te	sting undertaken. The	Cooling System							
II mecnan	ical inspection prior to	purchase and tr	nis can be arranged to	r an additional d	narge.	Coolant condition	~		
			SW SW		SW	Performance	~		
:		$=$ $\langle 0 \rangle$	3W 3W			Radiator / Hoses (visual)	~		
cratch dent	NE				M	Transmission	1		
ust	S SC W	 i		7/	S W	Operation	~		
paint def	ect NP				7171/1	Noise	~		
rack					SC W	Clutch			~
oin dent	sc de					CV joints	~		
ecals	- JIE				BID SW	Wheel bearings	~		
stone chi	/	$\mathbb{V}(0)$		200	**	Brakes			
significan	s sculis s	w	SPW SW		/ W	Performance	V		
ody Incr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
	os in windscreen.					Tyres (lowest observed trea	d depth	of tyre	es)
	rear window wiper arm	is missing.				Left front	T	.1	mm
						Right front		.3	mm
						Left rear	1	.3	mm
onditio	ns During Body Ins	nection:	Wet			Right rear	1	.6	mm
Oriditio	is builing body insp	pection.	vvet			Spare	<u> </u>	Yes	
nder Ca	rriage & Under Bor	net Inspectio	on Comments			Suspension			
						Suspension performance	V		
						Steering performance	V		
						Shock absorbers	<i>v</i>		
						Air Conditioning / Heater			
						Operation	V		Г
terior C	omments					Electrical / Accessories			
Seats	Good					Head lights	V		
Jeans						Tail lights	V		
Carpets	Good					Indicators	<i>v</i>		
Panels	Good					Dashboard warning lights	v		
rancis						Wipers (front & rear)	<i>v</i>		-
Dashboa	rd Good					Window winder FL	V		
						Window winder FR	V		
eneral (<u>Comments</u>					Window winder RL	V		
nterior C pillar has a bolt hole on right & left sides, where a cargo rack has been bolted in.					Window winder RR	V			
CD player	not working.					Rear view mirrors			
						Radio (basic test only)	<i>'</i>	-	_
						CD (basic test only)	~	V	
						Number of keys	1		<u></u>
	1 B . =					· 	1		
oad Con	ditions During Test	t Drive:	Wet			Central locking	<i>'</i>	-	_
ngine Tii	ming Mechanism:	Cambelt	<u> </u>			Remote locking	~	-	<u> </u>
ridence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
.acricc	o. cam ben neplac			14113.		Reversing camera			~