

Report ID: 18,582,698 Version: 2 12 Oct 2018 Created:

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A
Year:	2014	Registration:	HRD407	Reg Expiry:	23 Dec 2018	Engine			L
WoF Expiry:	18 Sep 2019	Odometer:	111,058 Kms	Good No:	18582698	Oil level	~		
VIN:	MNAUMFF50EW2967(Next Service:	118,844kms	Service Histor		Smoke & fumes	~		
			-,			Performance	~		
	port is not a warranty	aration is made	for and milago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	sc			715	HIVD	Operation	~		
PT = paint defe		F		$\left(\left \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIP				74116	CV joints			~
* = decals	sc 916					Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan			S D			Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Badges missing						Tyres (lowest observed tread depth of tyres)			
Budges mis	Sing					Left front	4	ŀ	mm
						Right front	5	5	mm
						Left rear	3.	5	mm
Conditions During Body Inspection: Wet						Right rear	4 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Carpets m	issing except dri	ver side			Tail lights	~		
Carpets		5 1				Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Ca Thach Date: 12 Oct 2018									

I have read and understood this condition guide.

Name:

Signature: