

## **Basic Vehicle Condition Guide**

Report ID: 18,582,928


Version:

Created: 02 Oct 2018

Make: Model: Holden Captiva 5 **Body Style:** SUV Year: 2014 Registration: HND83 Reg Expiry: 29 Dec 2018 WoF Expiry: **Odometer:** 23 Jul 2019 **Good No:** 85,713 Kms 18582928 VIN: KL3DA26U9EB038605 **Next Service:** 92000 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Underbody oxidisation

Interior Comment	<u>:S</u>
Seats	some marks
Carpets	Average
Panels	Good
Dashboard	Good

## **General Comments**

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: John Lindsay Date: 02 Oct 2018

_
ım
m
m
ım

I have read and understood this condition guide.

Name: .....

Signature: .....