

Tidy.

Turners Certified Imports 50 Point Check

Report ID: 18,583,234

Version:

Created: 01 Oct 2018

mm

mm

mm

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.


accredited inspection agency and been test driven up to sokm/n from				
Make: Volksw	agen Body St	tyle: Hatchback	Seats:	Good
Model: Golf	Odome	Odometer: 86,162 Kms		Good
Year: 2006	VIN:	WVWZZZ1KZ7W038157	Carpets:	Good
Under Carriage & Under Bonnet Inspection Comments			Panels:	Good


Dashboard: Good Timing Chain

General Comments Nice AWD R32.

Engine Timing Mechanism: Not Applicable **Evidence of Cam Belt Replacement:** Replaced At (odometer reading): Dry **Road Conditions During Test Drive:**

Electrical	
Battery	
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	
Reversing camera	•





Date: 01 Oct 2018