

Basic Vehicle Condition Guide

Report ID: 18,583,585


Version:

02 Oct 2018 Created:

Make: Model: Ford Fiesta **Body Style:** Hatchback Year: 2015 Registration: Reg Expiry: 26 Jul 2018 JFM455 WoF Expiry: **Odometer:** 27 Jul 2018 **Good No:** 18583585 15,422 Kms VIN: WF0CXXGAKCFL51430 **Next Service: Service History:** 20000 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | |
|-------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

Date: 02 Oct 2018 Inspected by: Xinghui Lin

Name:

| | Pass | Fail | N/A | | |
|------------------------------|--|---------|-----|--|--|
| Engine | | | | | |
| Oil level | > | | | | |
| Smoke & fumes | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | \(\triangle \) | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | \(\times \) \(\t | | | | |
| Clutch | ~ | | | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | | |
| Left front | 3 | .5 | mm | | |
| Right front | 3 | .5 | mm | | |
| Left rear | 3 | .5 | mm | | |
| Right rear | 3.5 | | mm | | |
| Spare | | Yes | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | V V | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | ~ | | | | |
| Dashboard warning lights | > | | | | |
| Wipers (front & rear) | \(\times \) | | | | |
| Window winder FL | > | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | | | ~ | | |
| Window winder RR | | | ~ | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | ~ | | | | |
| Number of keys | 2 | | | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | | | ~ | | |
| | | | | | |

Signature: