

Report ID: 18,584,051 Version: 1 Created: 01 Oct 2018

Make:	Nissan	Model:	Maxima	Body Style:	Sedan		Pass	Fail	N/A
Year:	2004	<b>Registration:</b>	ENJ687	Reg Expiry:	10 Nov 2018	Engine	1		
WoF Expiry:	12 Apr 2019	Odometer:	122,285 Kms	Good No:	18584051	Oil level	~		
VIN:	JN1BBUJ31A0003026	Next Service:	131000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	Coolant condition		
						Performance	~		
Key:	P	-0	SDR DR		<u>SD</u>	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent P = rurt SPT SC SPT						Operation	~		
R = rust ST SC ST						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals R SC 919 S PT						Wheel bearings	~		
SC = stone chips						Brakes			L
W = significant scuffs S W D R D R W						Performance	~		
Note: come defecte 8 blamiches may not be dienlayed in the diagram						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	•	oftyre	25)
Left front tyre outer and inner edge wear Right front tyre outer edge wear						Left front			mm
						Right front			mm
						Left rear	4		mm
							4		
Conditions During Body Inspection: Wet						Right rear	4 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Underbody & under bonnet oxidisation						Suspension			
onderbody	a under bornnet oxidis					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation	~		
Good						Electrical / Accessories			
Seats						Head lights	~		ļ
Carpets	Good					Tail lights	~		
	Good					Indicators	~		L
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		
Concret	ommonts					Window winder FR	~		<u> </u>
<u>General Comments</u>						Window winder RL	~		ļ
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	۲		
						Remote locking	2		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Increased by Lindsay							10		
Inspected by: John Lindsay Date: 01 Oct 2018									
I have read and understood this condition guide. Name:									