

Report ID: 18,584,120 Version: 2 Created: 02 Oct 2018

Make:	Mazda	Model:	Mazda6	Body Style:	Wagon		Pass	Fail	N/A
Year:	2010	Registration:	FLR377	Reg Expiry:	01 Mar 2019	Engine	1	1	
WoF Expiry:	10 Nov 2018	Odometer:	162,666 Kms	Good No:	18584120	Oil level	~		
VIN:	JM0GH10F200204787	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	<u>port is not a warranty</u> a guide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
diagnostic tes	ting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
					Р	Performance	~		
Key:	s sc s	-0	SPTP SP	-01-		Radiator / Hoses (visual)	~		
S = scratch	STE			NOG	Tan	Transmission	1		
D = dent R = rust	sc w			715	HILS	Operation	~		
PT = paint defe				$\left[\right] \left[\right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74114	CV joints	~		
* = decals	ssc 916			The		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant	scutts S S	$\neg \varnothing$	SD P	J Vr	Р	Performance	~		
Dealerteen		Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed trea	d depth	of tyre	es)
Rear left window fail						Left front 2 mm			
						Right front		<u>-</u> 1	mm
						Left rear			mm
Conditions During Podu Inspections						Right rear	2 mm 2 mm		
Conditions During Body Inspection: Wet						Spare			
Under Carriage & Under Bonnet Inspection Comments						Suspension	Yes		
Drive belt cr	racks	·				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Seals						Tail lights	v v		
Carpets	Carpets m	issing				Indicators			
	Poor						v		
Panels						Dashboard warning lights Wipers (front & rear)	~ ~		
Dashboa	rd Good					Window winder FL	-		
						Window winder FL	v		
General C	omments						~		
						Window winder RL	-	~	
						Window winder RR	V		
						Rear view mirrors	v		
						Radio (basic test only)	v		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	Drive:	Dry			Central locking	~		
Engine Tir	ning Mechanism:	Timina				Remote locking			~
-	of Cam Belt Replac	Timing (ement:		Kms:		Sat. Nav. (basic test only)			~
			lot Applicable	11115.		Reversing camera			~
Inspected	l by: Ca Thach					Date: 02 Oct 20	18		

I have read and understood this condition guide.

Name:

Signature: