

 Report ID:
 18,584,760

 Version:
 2

 Created:
 18 Feb 2019

Make:	Hyundai	Model:	Getz	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2008	Registration:	LKH316	Reg Expiry:	19 Feb 2019	Engine		. un	
WoF Expiry:	2008 18 Feb 2019	Odometer:	99,054 Kms	Good No:	18584760	Oil level	~		
VIN:	KMHBT51DR8U78550			Service Histor		Smoke & fumes			
viiv.		NEXT SEIVICE.	110220	Service mistor	y. NO	Performance	~		
	port is not a warranty						~		
This report is	a guide only. Conside sting undertaken. The	eration is made	for age and mileage	. Parts have not	t been dismantled or Vendor recommends	Noise	~		
	nical inspection prior to					Cooling System	r		1
						Coolant condition		~	
Key:	SC		S* SD		S	Performance	~		
S = scratch		(0)		300	\checkmark	Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust	s 96				SHUK	Operation	~		
PT = paint def	ect N				PT	Noise	~		
C = crack						Clutch			~
P = pin dent * = decals	PSC de			S	18445	CV joints	~		
SC = stone chi	ns U	10		10		Wheel bearings	~		
W = significant scuffs						Brakes		1	
-	W	\sim	*		Р	Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	may not be dis	olayed in the diagram	Hand Brake	~		
Window trims worn						Tyres (lowest observed tread depth of tyres)			
Right bottom sill dent						Left front	3	.0	mm
						Right front	3	.0	mm
						Left rear	6	.0	mm
Conditio	ns During Body Ins	pection:	Wet			Right rear	7	.0	mm
Contactor Datanage Dealy inspection. Incl						Spare		Yes	-
Under Ca	rriage & Under Bor	nnet Inspectio	on Comments			Suspension			
Surface rust	t in engine bay					Suspension performance	~		
						Steering performance	~		1
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		1
Interior Comments						Electrical / Accessories	-		
Seats	Average					Head lights	~		Τ
						Tail lights	~		+
Carpets	Average					Indicators	~		
Danala	door card	skin damage				Dashboard warning lights	~		-
Panels		-				Wipers (front & rear)	~		+
Dashboa	rd Good					Window winder FL	~		+
						Window winder FE	<i>v</i> <i>v</i>		
General (Comments					Window winder FR Window winder RL			
							v		
						Window winder RR	v		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
Engine Timing Mechanism: Cambelt						Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence	or Cam Beit Replac	ement: N	10	Kms:		Reversing camera			~
Inspected by: Jason Law Date: 03 Oct 2018									

I have read and understood this condition guide.

Name:

Signature: