

Report ID: 51,735 Version: 1 Created: 19 Oct 2018

Make:	BMW	Model:	Х3	Body Style:	SUV	] [	Pass	Fail	N/A
Year:	2007	Registration:	DTR151	Reg Expiry:	27 Aug 2019	Engine			
WoF Expiry:	17 Oct 2019	Odometer:	119,960 Kms	Good No:	18585431	Oil level	~		
VIN:	WBAPD72070WD5423	Next Service:	Just Serviced	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	avation is made	for one and miles as	Dauta hava nat	heen discontined or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	nis can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	V		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch							Transmission		
D = dent	s 6/6			The		Operation	~		
R = rust PT = paint def				$\prod$	JHH	Noise	~		
C = crack				+		Clutch	-		~
P = pin dent	HIC					CV joints	~		-
* = decals	6116			The	EII PR-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: son	ne defects & blemishes	may not be disr		Hand Brake	~		
Body Insp	pection Comments	Note: 5011		indy not be disp	ayea in the diagram			oftyre	) )
						Tyres (lowest observed tread depth of tyres)   Left front 5.0 mm			
								.0	mm
						Right front Left rear		.0	mm
							-	.0	
Conditions During Body Inspection: Dry						Right rear	3.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare	105		
	inage a onder bor	ince inspectie	connents			Suspension			
						Suspension performance	~		
						Steering performance	~		
		Shock absorbers	~						
						Air Conditioning / Heater			1
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			1
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	0000					Dashboard warning lights			
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General Comments						Window winder FR	~		
						Window winder RL	~		
						Window winder RR	~		-
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
- Engine Ti	ming Mechanism	T:				Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
	or Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: DM Auto's Date: 08 Oct 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....