

I have read and understood this condition guide.

Report ID: 18,585,918 Version: 1 30 Oct 2018 Created:

Signature:

Make:	Audi	Model:	A3	Body Style:	Hatchback			Pass	Fail	N/A
Year:	2013	Registration:	ation: LMA755 Reg Expiry: 27 Jun 2019			Engine				
WoF Expiry:	26 Oct 2019	Odometer:	69,889 Kms	Good No:	18585918	Oil level		~		
VIN:	WAUZZZ8P6DA06593	Next Service:	79800	Service Histor	y: No	Smoke & f	fumes	~		
						Performa	nce	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise		~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling Sy	stem			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant c	ondition	~		
						Performa	nce	~		
Key:	S SC	-0	P SC S P SC	-M-	S SC	Radiator /	'Hoses (visual)	~		
S = scratch D = dent						Transmissi	on			
B = rust SSC D S						Operation	ı	~		
PT = paint defe	ect NP	r I		$\left[\left(\right) \right]$	7011	Noise		~		
C = crack						Clutch				~
P = pin dent	HIP				74116	CV joints		~		
*= decals SSC 000						Wheel bea	Wheel bearings			
SC = stone chips W = significant scuffs						Brakes				
w = significant scurrs S SC S SC S SC S SC S SC						Performance		~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brak	ke	~		
<u></u>						Tyres (lowest observed tread depth of tyres)				es)
						Left front		4 mm		mm
						Right front		4 mm		mm
						Left rear		6 mm		mm
Conditions During Body Inspection: Dry						Right rear 6 r			mm	
						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspensio	n			-
						Suspensio	on performance	~		
						Steering p	performance	~		
						Shock abs		~		
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments Good						Electrical / Accessories				
Seats	Good					Head ligh	ts	~		
Carpets	Good					Tail lights		~		
	Card					Indicators	5	~		
Panels	Good						d warning lights	~		
Dashboa	Good					Wipers (fr	ont & rear)	~		
						Window v		~		
Concerté						Window v		~		
<u>General Comments</u>						Window v		~		
						Window v		~		
						Rear view		~		
							sic test only)	~		
						CD (basic test only)		~		
							Number of keys		2	
Road Conditions During Test Drive: Dry						Central locking		~		
Engine Timing Mechanism: Timing Chain						Remote locking		~		
						Sat. Nav. (basic test only)		~		
	or cam beit neplac		lot Applicable	11113.		Reversing	camera	~		
Inspecte	d by: Donovan Matar	а				۵	Date: 30 Oct 201	8		

Name: