

Report ID: 18,586,200 Version: 2 Created: 09 Oct 2018

Make:	Mazda	Model:	Mazda3	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2014	<b>Registration:</b>	HNL71	<b>Reg Expiry:</b>	22 Jul 2018	Engine		I	
WoF Expiry:	03 Sep 2019	Odometer:	30,568 Kms	Good No:	18586200	Oil level	~		
VIN:	JM0BM547810133160	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
					s	Performance	~		
Key:	SC	-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	sc			215	HIVS	Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent	HID				2414	CV joints	~		
* = decals	sc 916			The second	ALD S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S S S S						Performance	~		
Podylog	action Commonts	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments Stonechips on windscreen.						Tyres (lowest observed tread depth of tyres)			es)
Stoneenips on windscreen.						Left front 2 mm			mm
						Right front		2	mm
						Left rear		2	mm
Conditio	ns During Body Insi	pection.	Wot			Right rear		3	mm
Conditions During Body Inspection: Wet						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Dent in fror	nt muffler.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	1				I	Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
Drives well.						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	I	
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
								1	1
Inspected by: Roger King Date: 09 Oct 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....