

Report ID: 18,586,608 Version: 2 11 Oct 2018 Created:

Make:	Toyota	Model:	Platz	Body Style:	Sedan		Pass	Fail	N/A
Year:	2000	<b>Registration:</b>	FYY340	Reg Expiry:	01 Apr 2019	Engine	1		1
WoF Expiry:	04 Jul 2019	Odometer:	90,770 Kms	Good No:	18586608	Oil level	~		
VIN:	7AT0H63RX10056361	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	nis can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0	S SP			Radiator / Hoses (visual)	~		-
S = scratch						Transmission	•		<u> </u>
D = dent	s sc			The	SP SP	Operation	~		
R = rust PT = paint defe				$\prod$	JHH	Noise	~		
C = crack					SC	Clutch	•		~
P = pin dent	Ho					CV joints	~		
* = decals	sc PIK			AL.	ELTR'S	Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs W S S P W						Performance	~		T
		Noto: con				Hand Brake			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							/ /	ofture	
						Tyres (lowest observed tread depth of tyres)			
								.5	mm
						Right front		.5	mm
						Left rear	4	-	mm
Conditions During Body Inspection: Wet						Right rear 4.0 mm			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	mage & onder bor	metinspectic	<u>In comments</u>			Suspension			
						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	iu ș					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
LH wing mirror not working /noisy Drive belt noisy						Window winder RR	~		
	;					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
			**			Remote locking	~		1
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
							I		1
Inspected	d by: Xinghui Lin					Date: 10 Oct 20	18		

I have read and understood this condition guide.

Name: .....

Signature: .....