

Basic Vehicle Condition Guide

Report ID: 18,587,527


Version:

03 Oct 2018 Created:

Make: Model: Hilux **Body Style:** Utility Toyota Year: Registration: FWF624 Reg Expiry: 29 Dec 2018 2011 WoF Expiry: **Odometer: Good No:** 18587527 13 Mar 2019 186,154 Kms VIN: MR0EZ12G904010841 **Next Service: Service History:** 191,000 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	drivers seat ripped passenger seats good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

lan Dunn

Evidence of Cam Belt Replacement: Yes

	Pass	Fail	N/A	
Engine	1 433	ıuli	'\/ \	
Smoke & fumes	V			
Performance	\(\times \)			
Noise Cooling System				
Coolant condition	.,			
Performance				
———				
Radiator / Hoses (visual)				
Operation				
Noise	\(\times \)			
Clutch				
CV joints				
<u> </u>				
Wheel bearings Brakes				
Performance				
	-			
Hand Brake Tyres (lowest observed trees	l donth	of to)e)	
Tyres (lowest observed tread depth of tyres) Left front 5 4 mm				
		.4	mm	
Right front Left rear	5.3		mm	
	4.3		mm	
Right rear	4.4		mm	
Spare Yes				
Suspension Suspension performance	.,			
Steering performance	<i>V</i>			
	./			
Shock absorbers Air Conditioning / Heater				
Operation Electrical / Accessories				
Head lights				
Tail lights	•			
Indicators	·/			
Dashboard warning lights	•			
Wipers (front & rear)	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
Window winder FL	· ·			
Window winder FR	~			
Window winder RL	1/			
Window winder RR	V			
Rear view mirrors	<i>y</i>			
Radio (basic test only)	V V			
CD (basic test only)	<i>v</i>			
Number of keys				
Central locking	2			
Remote locking	1/			
Sat. Nav. (basic test only)			.,	
Reversing camera			<i>y</i>	
eversing camera				

I have read and understood this condition guide.

Name:

151,511

Kms:

Signature:

03 Oct 2018

Date: