

Basic Vehicle Condition Guide

Report ID: 18,587,543

Pass

1

~

V

1

/

Version: 5

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Operation

Noise

Clutch

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Left rear

Right rear

Suspension

Spare

Right front

Coolant condition Performance

Radiator / Hoses (visual)

Created: 30 Apr 2019

Fail

N/A

mm

mm

mm

mm

1


0

No

Make: Volkswagen Model: Crafter **Body Style:** Van Year: 2017 Registration: KLK16 **Reg Expiry:** 30 Apr 2019 **WoF Expiry: Odometer:** 16 Mar 2020 60,198 Kms **Good No:** 18587543 VIN: WV1ZZZ2EZH6003783 **Next Service:** 83,000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Dry

Under Carriage & Under Bonnet Inspection Comments

Hoist inspection not done due to oversize

Conditions During Body Inspection:

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Inspected by:

Brake wear indication on dashboard Right headlamps low beam not working

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Bobby Zhong

Evidence of Cam Belt Replacement: Kms: No

Suspension performance 1 Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights V Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR 1 Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera 30 Apr 2019 Date:

Signature:

Name: