

Basic Vehicle Condition Guide

Report ID: 18,587,562

Version: 1

Engine

Created: 07 Oct 2018

Fail


Pass

N/A

Make: Model: Hyundai **Body Style:** SUV Tucson Year: 2008 Registration: Reg Expiry: ERF737 18 Sep 2019 **WoF Expiry: Odometer: Good No:** 29 Sep 2018 373,132 Kms 18587562 VIN: KMHJN81BR8U871232 **Next Service: Service History:** 370,000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chip on front windscreen FR, RR, RL doors inner handle portion torn Rear wiper noisy

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	<u>S</u>
Seats	Average
Carpets	Average
Panels	Poor
Dashboard	Good

General Comments

Inspected by:

Steering getting tight in certain positions Knocking noise from front

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

Oil level	~		
Smoke & fumes	~		
Performance	<i>V V</i>		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			•
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	1	.6	mm
Right front	1.6		mm
Left rear	3		mm
Right rear			mm
Spare	Yes		
Suspension	•		
Suspension Suspension performance		~	
<u> </u>		ν ν	
Suspension performance	<i>V</i>	ν ν	
Suspension performance Steering performance	~	<i>V</i>	
Suspension performance Steering performance Shock absorbers	V	<i>V</i>	
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater	V	<i>V</i>	
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation	<i>V</i>	V V	
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories	V V V V	V V	
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights	V V V V V	V V	
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights		V V	
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators	~	V V	
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights	v v	<i>V</i>	
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear)	v v	V V	
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL	v v	\(\times \)	
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR	\(\times \) \(\t	\(\times \)	
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL	V V V V	\(\times \)	
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR	V V V V	\(\times \)	
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors	V V V V V		
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RR Rear view mirrors Radio (basic test only)	V V V V V V		
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)	V V V V V V		
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	V V V V V V		

I have read and understood this condition guide.

Mathew Varghese

Name:

Signature:

07 Oct 2018

1

Reversing camera