

Report ID: 18,587,673 Version: 1 Created: 03 Oct 2018

Make:	Mazda	Model:	Mazda6	Body Style:	Sedan		Pass	Fail	N/A
Year:	2007	Registration:	EAJ766	Reg Expiry:	27 Jul 2019	Engine	1		
WoF Expiry:	26 Jan 2019	Odometer:	137,585 Kms	Good No:	18587673	Oil level	~		
VIN:	JM0GG103200545443	Next Service:	144106	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch	Re	A U			X.	Transmission	•		
D = dent	sc			The		Operation	~		
R = rust PT = paint def				$\prod$	1711A	Noise	~		
C = crack				$+ \mathbf{\nabla}$		Clutch	•		~
P = pin dent					세비	CV joints	~		•
* = decals	sc 916			The	ELLAR S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S SC SC W S						Performance	~		
		Note: som		may not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread		oftvre	() ()
						Left front 6 mm			
						Right front			 mm
						Left rear	6		mm
							4		
Conditions During Body Inspection: Wet						Right rear 4 mm Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
Clean						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	-		
							~		
						Air Conditioning / Heater			
Interior Comments						Operation V			
Good						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear) Window winder FL	~		
						Window winder FL Window winder FR	<b>v</b>		
General (	Comments					Window winder FR Window winder RL	V		
							~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	: Drive:	Wet			Central locking	~		
Engine Ti	ming Mechanism:	Timina (				Remote locking	~		
						Sat. Nav. (basic test only)			~
		Ciriciit. N	lot Applicable	11115.		Reversing camera			~
Inspected by: Stuart Melbourne Date: 03 Oct 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....