

Report ID: 18,587,747 Version: 1 Created: 09 Oct 2018

Make:	Land Rover	Model:	Freelander	Body Style:	SUV		Pass	Fail	N/A
Year:	2001	Registration:	ZT5252	Reg Expiry:	08 Feb 2019	Engine			
WoF Expiry:	2001 06 Oct 2018	Odometer:	213232 222,212 Kms	Good No:	18587747	Oil level	~		
VIN:	SALLNABG11A584198		,	Service Histor		Smoke & fumes	~		
	SALENADOTTAS04190		228000		. 110	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends									
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
Key:	S SC W		S SC W S SC		S SC	Performance	~		
S=scratch						Radiator / Hoses (visual)	al) 🖌		
D = dent						Transmission			
R = rust						Operation	~		
PT = paint defect						Noise	~		
C = CraCk						Clutch			~
P = pin dent * = decals SC DD SC						CV joints	~		
* = decals SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
S SC W S SC S SC W S						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Right rear window works from door switch						Tyres (lowest observed tread	d depth	of tyre	es)
Sunroof not working has rust Stone chip front window screen						Left front 4.3			mm
	none window sciech					Right front	4	.8	mm
						Left rear	4	.6	mm
Conditions During Body Inspection: Dry						Right rear	4.7 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
No underbo	ody inspection					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	drivers sea	t tear				Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good			Dashboard warning lights	~				
	Good					Wipers (front & rear)	~		
Dashboa	ru					Window winder FL	~		
с Г						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	'es	Kms: 21	0,207	Reversing camera			~
·						- ···-			
Inspected by: Jamie Cook Date: 09 Oct 2018									
I have read and understood this condition guide. Name:									