

Report ID: 18,588,181 Version: 6 17 Jan 2019 Created:

Signature:

Make:	Holden	Model:	Adventra	Body Style:	SUV		Pass	Fail	N/A
Year:	2006	Registration:	DMF94	Reg Expiry:	22 Aug 2019	Engine			
WoF Expiry:	28 Jun 2019	Odometer:	215,087 Kms	Good No:	18588181	Oil level	~		
VIN:	6G1ZM84715L540900	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
			S S P		Р	Performance	~		
Key:		-0		-(0)-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust S D S D						Operation	~		
PT = paint defe	ect NP	r I		$\left(\left\ \left(\right) \right) \right)$	701A	Noise	~		
C = crack					PT	Clutch			~
P = pin dent	sc dle				7414	CV joints	~		
* = decals				To .		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	S		S P S		S P	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
Boot door light lens broken						Tyres (lowest observed tread depth of tyres)			
						Left front	Left front 3		
						Right front		3	mm
						Left rear	3	3	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance		~	
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Correcto	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Roof lining	g sagging				Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	iru					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
Front suspension noise Noise from rear while braking						Window winder RR	~		
	-					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Г						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Mathew Varghese Date: 17 Jan 2019									
Date. 17 Jail 2017									

I have read and understood this condition guide.

Name: