

Report ID: 18,588,264 Version: 3 05 Jan 2019 Created:

Make:	Holden	Model:	Crewman	Body Style:	Utility		Pass	Fail	N/A
Year:	2007	Registration:	FDP151	Reg Expiry:	18 Feb 2019	Engine			
WoF Expiry:	14 Nov 2019	Odometer:	196,086 Kms	Good No:	18588264	Oil level	~		
VIN:	6G1ZK34B16L975415	Next Service:	205,000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	avation is made	for one and miles as	Danta hava nat	heen discontined or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:		-0	S S		s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent SW 66						Operation	~		
R = rust PT = paint defe				Γ	JHIH	Noise	~		
C = crack					SC SC	Clutch	•		~
P = pin dent						CV joints			~
* = decals	SPSC PK				EIR SD	Wheel bearings	~		•
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: som	ne defects & blemishes	may not be disp		Hand Brake	~		
	pection Comments	1016.301	le delects & blemisnes	s may not be disp	layed in the diagram		•	ofturo	
Scratch on windscreen Paint defect on canopy roof						Tyres (lowest observed tread depth of tyres) Left front 3			
	t on carlopy roor						3		mm
						Right front Left rear	3		mm
							7 mm		
Conditions During Body Inspection: Dry						Right rear	7 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	inage a onder bor	meenspeede	<u>eominents</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Poor						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
Concret	ommonts					Window winder FR	~		
	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
	ning Mashering	T:	[°] hain			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Jason Law Date: 05 Jan 2019									
Inspected by, Jason Law Date: 05 Jain 2019									

I have read and understood this condition guide.

Name:

Signature: