

Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

		Air Conditioning / Heater				
			Operation	×		
Interior Comments			Electrical / Accessories			
Seats	Average		Head lights	×		
Carpets	Average		Tail lights	×		
			Indicators	×		
Panels	Average		Dashboard warning lights	×		
	Average		Wipers (front & rear)	×		
Dashboard			Window winder FL	×		
		Window winder FR	×			
<u>General Comments</u>			Window winder RL	×		
			Window winder RR	×		
			Rear view mirrors	×		
		Radio (basic test only)	×			
			CD (basic test only)	×		
			Number of keys	1		
Road Conditions During Test Drive: Dry			Central locking	×		
· · · · · · · · · · · · · · · · · · ·		Remote locking	×			
Engine Timing Mechanism: Timing Chain		Sat. Nav. (basic test only)			×	
Evidence of Cam Belt Replacement: Not Applicable Kms:			Reversing camera			x

I have read and understood this condition guide.

Inspected by:

Scott Willoughby

Name:

Signature:

23 Oct 2018

Date:

1

09 Nov 2018

Fail

N/A

x

mm

mm

mm

mm

X

8.0

8.0

8.0

4.0

X

x

x

Yes

Tyres (lowest observed tread depth of tyres)

Hand Brake

Left front

Left rear

Right rear

Suspension

Suspension performance

Steering performance

Shock absorbers

Spare

Right front