

## **Basic Vehicle Condition Guide**

Report ID: 18,588,839


Version: 2

Created: 10 Oct 2018

Make: Model: Octavia **Body Style:** Wagon Skoda Year: 2014 Registration: HRL535 Reg Expiry: 05 Apr 2019 **WoF Expiry: Odometer:** 28 Sep 2019 **Good No:** 18588839 160,881 Kms VIN: TMBKJ7NE8F0037051 **Next Service: Service History:** 177,000 Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments	5
Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

**General Comments** 

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jeff Luke Date: 09 Oct 2018

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\( \times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	V		
Radiator / Hoses (visual)	~		
Transmission			•
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes		•	•
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	3	.0	mm
Right front	3	.0	mm
Left rear	3	.0	mm
Right rear	3	.0	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V V V V V V V V V V V V V V V V V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			<b>'</b>

I have read and understood this condition guide.

Name <sup>,</sup>			