

Report ID: 18,589,139 Version: 1 Created: 10 Oct 2018

Make:	Mazda	Model:	Bt-50	Body Style:	Utility		Pass	Fail	N/A
Year:	2011	Registration:	GAQ240	Reg Expiry:	18 Nov 2018	Engine	I		1
WoF Expiry:		Odometer:	145,829 Kms	Good No:	18589139	Oil level	~		
VIN:	MM0UNY0E40090382	Next Service:		Service Histor	y: No	Smoke & fumes	~		+
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	S SC	-0	SC S P SC	-161-	S D	Radiator / Hoses (visual)	~		
S = scratch						Transmission	•		
D = dent						Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint defect C = crack						Clutch	~		
P = pin dent	Ho					CV joints	~		
* = decals	s sc pp			AL.	ELFR SD	Wheel bearings	-		
SC = stone chips						Brakes	~		
W = significant scuffs SC SP SC S						Performance			
Nata como defecto 9 blamichos may not be displayed in the diagram							V		
Body Inspection Comments						Hand Brake	/ /	of +	
Canopy needs paint ,major stone chip windscreen ,						<b>Tyres</b> (lowest observed tread depth of tyres)			
						Left front		7	mm
						Right front		7	mm
						Left rear		7	mm
Conditions During Body Inspection: Dry						Right rear	7	7	mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	mermspectic	<u>on comments</u>			Suspension			
						Suspension performance	~		$\vdash$
						Steering performance	~		ļ!
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Interior Comments Average						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General (	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
						<b></b>			
Inspected by: Donovan Matara Date: 10 Oct 2018									
I have read and understood this condition guide. Name:									