

Report ID: 18,589,852 Version: 1 17 Oct 2018 Created:

Make:	Mazda	Model:	Bt-50	Body Style:	Utility		Pass	Fail	N/A
Year:	2012	Registration:	GKQ817	Reg Expiry:	27 Mar 2019	Engine			
WoF Expiry:	31 Jul 2019	Odometer:	109,485 Kms	Good No:	18589852	Oil level	~		
VIN:	MM0UP0YF10011686		114000	Service Histor		Smoke & fumes	~		
			114000		. 110	Performance	~		
	port is not a warranty					Noise	-	~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	S SC	-0	S P SC S P SC		P SC	Radiator / Hoses (visual)	~		
S = scratch D = dent D = mut						Transmission			
						Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack				+		Clutch	~		
P = pin dent						CV joints	~		
* = decals	SDSC 91			AL-	S D SC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S D SC						Performance	~		
		Note: com				Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	ofture	
LH sill dented ,badges missing from the tailgate,tailgate light cracked ,					Tyres (lowest observed tread depth of tyres)				
						Left front	6		mm
						Right front Left rear	6		mm
						6 mm		-	
Conditions During Body Inspection: Dry						Right rear	6 mm		
Under Carriage & Under Bonnet Inspection Comments					Spare	Yes			
Minor oil leak ,						Suspension Suspension performance			
	ur,					Steering performance	~		
						Shock absorbers	~		
							~		
						Air Conditioning / Heater			
Interior Comments						Operation V			
drivers seat worn wear and tear stains						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
General (omments					Window winder FR	~		
General Comments Noisey rattle coming from front of motor sounds like one of the pulley wheels are loose,						Window winder RL		~	
, í	5					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Ti	ming Mechanism:	Timing				Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Donovan Matara Date: 17 Oct 2018									

I have read and understood this condition guide.

Name:

Signature: