

Report ID: 18,589,881 Version: 1 08 Oct 2018 Created:

Make:	Holden	Model:	Vectra	Body Style:	Sedan		Pass	Fail	N/A
Year:	2002	Registration:	AZZ570	Reg Expiry:	01 Apr 2019	Engine			
WoF Expiry:	28 Sep 2019	Odometer:	140,686 Kms	Good No:	18589881	Oil level	~		
VIN:	W0L0JBF1911219884	Next Service:	143723	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	V		
						Performance	V		
Key:		-0	PT SC	-01-		Radiator / Hoses (visual)	V		
S = scratch						Transmission			
D = dent R = rust S PT SC S PT SC						Operation	V		
PT = paint defect						Noise	V		
C = crack						Clutch	~		
P = pin dent	HE				74116	CV joints	~		
* = decals SC 919 SC						Wheel bearings	V		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Podylog	action Commonts	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	V		
Body Inspection Comments Left sill scratch						Tyres (lowest observed tread depth of tyres)			
Chips in screen					Left front 4.0 m			mm	
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear		.0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	V		
						Shock absorbers	V		
						Air Conditioning / Heater	1		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	, ivelage					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	L	
Road Conditions During Test Drive: Dry						Central locking	~		
	-		- ' J			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	'es	Kms: 93	3,833	Reversing camera			~
Inspected by: Greg Morgan Date: 05 Oct 2018									

I have read and understood this condition guide.

Name:

Signature: