

Report ID: 18,589,921 Version: 1 Created: 24 Oct 2018

Make:	Ford	Model:	Fiesta	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2012	Registration:	GPU246	Reg Expiry:	22 Nov 2018	Engine			
WoF Expiry:	02 Nov 2019	Odometer:	41,247 Kms	Good No:	18589921	Oil level	~		
VIN:	MNBJXXARJJCD24679	Next Service:	38,400kms	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0	SD S			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust PT = paint defect C = crack						Operation	~		
						Noise	~		
						Clutch			~
P = pin dent						CV joints	~		
*= decals SC 999 S						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SW SW S S S S						Performance	 ✓ 		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Vehicle comes with a run flat kit, (panda kit). Has no spare tyre.						Tyres (lowest observed tread	served tread depth of tyres)		
Venicie comes with a run hat kit, (panda kit). Has no spare tyre.						Left front	6.	6.4 mm	
						Right front	6.	2	mm
						Left rear		.4	mm
Conditions During Body Inspection: Dry						Right rear	6.	6.0 m	
						Spare No			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
L]						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General (<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
L						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
Inspected by: Jason Young Date: 24 Oct 2018									
I have read and understood this condition guide. Name:									